Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2063Work Order Type: WeatherizationAudit Name: 14014SO2063

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2063 FLINTVILLE, TN 37335

Alt. Client ID: LINCOLN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO2063
Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2063 Report Run On: 5/21/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 4

Measures

Measure 1 AIR	Components					Inspected			
2. INST	LK ALL WINDOWS TALL STORM DOOR HAF AN & SERVICE UNIT	RDWARE	ON FR	ONT DOOF	₹				
	Estimated Actual								
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Miscellaneous Supplies	Misc Material	Each	1						
2 Labor	LABOR	Hour							
Other Detail									
			Measur	e Sub Total:] ;	Sub Total:		
Measure 2 COC	OL SEAL			Componen				Inspected	
Comment		Units		Estimated	<u> </u>	Ofv	Actual		
	OL SEAL Description / Comment COOL SEAL ROOF	<i>Units</i> Each	Qty 1	•		Qty		Inspected Total	
Comment # Material / Labor	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual		
Comment# Material / Labor1 Other	Description / Comment COOL SEAL ROOF	Each	Qty	Estimated	<u> </u>	Qty	Actual		
# Material / Labor 1 Other 2 Labor	Description / Comment COOL SEAL ROOF	Each	Qty	Estimated	<u> </u>	Qty	Actual		
# Material / Labor 1 Other 2 Labor	Description / Comment COOL SEAL ROOF	Each	Qty	Estimated	<u> </u>	Qty	Actual		
# Material / Labor 1 Other 2 Labor	Description / Comment COOL SEAL ROOF	Each Hour	Qty 1	Estimated	<u> </u>		Actual		

Report Run On: 5/21/2010

	LYBOARD			Componen	its			Inspected
	AIR DRAIN PIPE / REPA TION / REPAIR DUCT V							
		Estimated Actual						
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Misc Material	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Measure 4 Fix I	mproper Venting (Cloth	nos Dryor						
	• • •	ies Diyei)	Componer Estimated				Inspected
# Material / Labor		Units		Estimated Unit Cost		Qty	Actual Unit Cost	Inspected Total
# Material / Labor1 Health and Safety Items	Description / Comment	·	Qty	Estimated	1	Qty	Actual	
1 Health and Safety	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
1 Health and Safety Items	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
1 Health and Safety Items2 Labor	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
1 Health and Safety Items2 Labor	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
1 Health and Safety Items2 Labor	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1 1	Estimated	1		Actual	

Report Run On: 5/21/2010

-	Measure 5 Smo	ke Detector is Needed			Componen	its			Inspected	
C	omment									
				Estimated		1	Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Smoke / Carbon detector	Each	1						
2	Labor	Labor	Hour	1						
C	Other Detail									
] []			
					[] []			
				Measur	e Sub Total:		•	Sub Total:		
	-	or Barrier Needed ement/Crawlspace)			Componen	nts			Inspected	
					Estimated	1		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	Basement / crawlspace vapor barrier	Each	1						
2	Labor	Labor	Hour	1						
C	Other Detail						1			
_				Measur	e Sub Total:		,	Sub Total:		
	Field Notes:									
_			Work Or	der Gra	and Total:		Gran	d Total:		

Report Run On: 5/21/2010